

Rating Scale: 1=Excellent, 5=Poor

Date	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
clean out											
repairs											
1/4/2017	711 w olive									replaced broken cap	1/4/2017
1/4/2017	815 w pine									replaced broken cap	1/4/2017
1/4/2017	1419 s oakland									replaced missing cap	1/4/2017
1/4/2017	420 s elgin									replaced broken cap	1/4/2017
2/13/2017	615 w freeman									replaced broken cap	2/13/2017
2/13/2017	609 w pine									replaced cap with holes in it	2/13/2017
3/2/2017	510 e maupin									disconneted servivce with cap	3/2/2017
3/22/2017	610 w broadway									replaced 2 caps	3/22/2017
3/22/2017	860 w morgan									replaced broken cap	3/22/2017
3/29/2017	216 s dunnegan									replaced broken cap	3/29/2017
4/13/2017	404 n williams pl									replaced missing cap	4/13/2017
4/13/2017	311 n williams av									replaced broken cap	4/13/2017
4/13/2017	143 n barker av									replaced 3 caps with holes in it	4/13/2017
4/18/2017	217 n rechow									replaced missing cap	4/18/2017
4/18/2017	1422 w fairplay									replaced missing cap	4/18/2017
										replace 5 feet of service in creek cause it was busted and concrete over it to keep it from washing out.	
5/16/2017	404 e freeman										5/16/2017
										replaced 15 feet of service because of busted cleanout and 45 we moved new cleanout out of the flow line of the ditch	
5/16/2017	421 n wilson									dug 3 cleanout up because of I&I	5/16/2017
5/22/2017	n sunset in field									capped them of a main	5/22/2017

City of Bolivar  
Inflow and Infiltration Sources Confirmed

2017

Rating Scale: 1=Excellent, 5=Poor

Date	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
6/6/2017	211 n rechow									replaced broken cap	6/6/2017
6/13/2017	119 n park									disconneted servivce with cap	6/13/2017
6/13/2017	davis prperties									fixed broken stand pipe	6/13/2017
6/13/2017	davis prperties									fixed manhole lid d4-mh-070	6/13/2017
7/12/2017	1535 n canton west of 1530									fixed broken stand pipe	6/13/2017
7/12/2017	hedgewood									fixed broken stand pipe	7/12/2017
7/12/2017	1780 e division									replaced missing cap	7/12/2017
7/13/2017	1018 w locust									replaced vented cap	7/13/2017
7/13/2017	1025 w chestnut									replaced missing cap	7/13/2017
7/13/2017	303 n williams									replaced broken cap	7/13/2017
9/14/2017	1630 s meadow ln									fixed broken stand pipe	9/14/2017
9/14/2017	1431 s meadow ln									replaced broken cap	9/14/2017
9/14/2017	1421 jones st									replaced broken cap	9/14/2017
9/14/2017	1690 s meadow ln									fixed broken stand pipe	9/14/2017
9/14/2017	1581 w jones										9/14/2017
9/14/2017	bolivar land corp									replaced missing cap	9/14/2017
9/14/2017	bolivar land corp									replaced missing cap	9/14/2017
9/19/2017	816 e college									replaced broken cap	9/19/2017
9/25/2017	1765 meadow ln									capped at main	9/25/2017
9/28/2017	2103 n northwood									replaced broken cap	9/28/2017
9/28/2017	2017 n northwood									replaced broken cap	9/28/2017
10/2/2017	1031 s carl st									replaced missing cap	10/2/2017
10/2/2017	1105 s carl									replaced missing cap	10/2/2017
10/12/2017	2875 s orchard									replaced missing cap	#####
10/12/2017	2720 s orchard									replaced missing cap	#####
12/4/2017	611 n russell									replaced broken cap	12/4/2017

City of Bolivar  
Inflow and Infiltration Sources Confirmed

2017

Rating Scale: 1=Excellent, 5=Poor

Date	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
					Size & Type of Main	# of Feet	Work Performed	COND. MH #1	COND. MH #2	remark	date repaired
4/26/2017	polk health cen.	x	e5-mh- 030	E5-MH- 25	8in	15feet	x	BAD	GOOD	removed e5-030 and replaced it with a stand pipe hook on to pvc that had been replace all the way to n barker in the past	4/26/2017
5/8/2017	simmit and main	x	f7-mh- 172	F3-MH- 182	8in	40feet	x	BAD	GOOD	replace manhole f7-172 (this was a flash manhole that did not line up with 6in hide west down summit. We installed new manhole 5 feet to the south, also laid 35 feet down simmit on the south side hooked the 6 back up to the 8. We will need to go back in the furture and lay a new line down summit and hook up to 8in pvc. (this will eliminate the old 6in in summit street.) We also eliminated to old taps..	5/8/2017

## Inflow and Infiltration Sources Confirmed

Date	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
5/31/2017	1405 w locust st	x	e4-mh- 165	e4-mh- 164	8in	30feet	x	GOOD	GOOD	We replaced 25 feet of clay pipe and 5 feet of pvc that had been spot repaired in the past. ( we did this because the spot repair had sattled down and there was a large piece of clay pipe in the flow line.) also replace one tap.	5/31/2017

Inflow and Infiltration Sources Confirmed

Date clean out repairs	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
------------------------------	----------	--------	--------	------------------------	-----------	-------------------	------------	----------------	----------------	--------	------------------

City of Bolivar

### Inflow and Infiltration Sources Confirmed

2017

Rating Scale: 1=Excellent, 5=Poor

Date	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
------	----------	--------	--------	------------------------	-----------	-------------------	------------	----------------	----------------	--------	------------------

City of Bolivar

### Inflow and Infiltration Sources Confirmed

2017

Rating Scale: 1=Excellent, 5=Poor

Date	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
------	----------	--------	--------	------------------------	-----------	-------------------	------------	----------------	----------------	--------	------------------

City of Bolivar

### Inflow and Infiltration Sources Confirmed

2017

Rating Scale: 1=Excellent, 5=Poor

Date	Location	MH # 1	MH # 2	Size & Type of Main	# of Feet	Work Performed	Resolution	COND. MH #1	COND. MH #2	Remark	Date Repaired
------	----------	--------	--------	------------------------	-----------	-------------------	------------	----------------	----------------	--------	------------------